

ABRASIVE BLASTING, STRIPPING AND PAINTING POLICY

This policy applies to all abrasive blasting, paint stripping and painting activities undertaken at Jandakot Airport, including aircraft.

Abrasive blasting, stripping and painting are activities that can impact the soil, water and air quality of the airport. They must only be carried out if the activity is permitted within the lease agreement with Jandakot Airport Holdings and an Operational Environmental Management Plan (OEMP) has been approved.

Abrasive Blasting

- Blasting activities must comply with the *Environmental Protection (Abrasive Blasting) Regulations 1998* and the WorkSafe Code of Practice – Abrasive Blasting.
- Abrasive blasting must occur in a blasting chamber if it is practical to do so. If blasting occurs outside of a chamber, no visible dust shall escape the premises or otherwise impinge on the health, property, or enjoyment of other airport users.
- All waste generated from blasting activities must be contained, cleaned up and disposed of to an appropriate landfill or treatment facility.

Paint Stripping

- All wastes from stripping and treating activities must be contained and stored using appropriate bunding in accordance with AS/NZS 1940 Storage and Handling of Flammable and Combustible Liquids.
- Solid and liquid wastes must be disposed of in an appropriate manner by a licensed contractor. Receipts must be retained for 3 years as proof of correct disposal.
- Where applicable, relevant licenses/permits must be obtained from the appropriate regulatory authorities.

Painting

Painting, with the exception of touch-up painting (defined as painting scratches, small dents and chips etc) must also occur within the following guidelines:

- Spray painting must only be conducted in a designated spray booth, designed in accordance with AS/NZS 4114 Spray Painting Booths. Aircraft painting must not occur outside.
- Spray painting must be conducted in line with the WorkSafe Code of Practice – Spray Painting.
- Storage, bunding and disposal of liquids used in the painting process must be in accordance with AS/NZS 1940 Storage and Handling of Flammable and Combustible Liquids.
- Cleaning and maintenance of spray booths must be in accordance with AS/NZS 4114.